

This Paper describes Banksia Hill's physical infrastructure and documents the changing character of the physical environment leading up to the riot on 20 January 2013. It also documents damage to the buildings and the nature of remedial work undertaken.